

Project Profile

Plastic Pipe Repair, Sodium Hypochlorite Tank



High concentrations of bleach had caused the bung threads in this 5,000 gallon tank to leak. Plastic "welding" held up for only one year. The waste water utility contacted **ADVANCED Polymer Repairs** in the hope that **ADVANCED** had a "magic bullet" solution. A high performance, chemical resistant repair system was specified.

In house staff performed the repairs in less than an hour under the experienced eye of Jim Krasnov of **ADVANCED**.

About \$50 of product saved the utility several thousand dollars in replacing the tank. As of this writing, about 5 years later, the maintenance staff reports "NO LEAKS!"



We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

Copyright 2000

www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

856-691-7343