

Project Profile

Concrete Floor & Expansion Joint Repair



The main aisle between two warehouse areas was exposed to constant, heavy forklift traffic. The expansion joint edge started to crack and the concrete surrounding it had spalled and was failing. It was costing the property owner substantial money in lost productivity, merchandise damage along with damage to the forklifts. **ADVANCED Polymer Repairs** had a long-term relationship with the owner and was told to “Fix it”.

Working over a weekend **ADVANCED** saw cut a perimeter and saw cut the expansion joint back to stable concrete. The expansion joint and work area were repaired with a 100% epoxy system which has a compressive strength of over 12,000 p.s.i. The joint was then saw cut open and filled with a unique polyurethane expansion joint material which has excellent adhesion to concrete, can take the constant pounding of forklifts and is flexible enough to allow the joint the needed movement.

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

www.AdvancedGroupUSA.com
ADVANCED
Polymer Repairs™
856-691-7343