

# Project Profile

## Waterproofing & Coating



This manufacturing plant had a corroded steel facade which leaked rain water into the building due to corrosion around the windows. The **ADVANCED Polymer Repairs** team was called in because they have established a long track record of success with the building owner on other projects.

In this closeup you can see that the flashing between the corrugation and the steel window frames had rusted away completely allowing water to run into the production floor area.



The building manager said he had a dozen companies willing to paint the facade but could find no one to solve the leaking. **ADVANCED** solved the problem through knowhow and great products

**On Budget**  
**On time**  
**Every Time**

**ADVANCED**  
Polymer Repairs

**856-691-7343**





