

## Project Profile Corrosion in Air Handlers



The air handlers at this Atlantic City casino had suffered severe corrosion from the salt air environment. Any coating used to effect the repair had to be extremely low in odor because of the risk of having to close the casino floor. Grit blasting could not be used for fear of dust entering public areas so surface preparation was minimal.



The problem was solved by **ADVANCED Polymer Repairs** with a highly corrosion resistant primer which would adhere to the poorly prepared surface. This was then overcoated with two coats of a flexible, corrosion resistant coating.

The assistant facility manager said that the only other option was to replace the air handlers at a cost of approximately \$100,000.

**On Budget  
On Time  
Every Time™**

**ADVANCED**  
Polymer Repairs

**856-691-7343**





