

## Project Profile Gas Station Bathroom Floor



The owner of this chain of gas stations contacted **ADVANCED Polymer Repairs** for an inexpensive fix for bathroom floors which could be carried out by in house maintenance staff. A member of the **ADVANCED** group spent a few hours demonstrating the correct surface preparation, mixing and application of a high-performance concrete repair system. This system has a compressive strength of over 12,000 psi and is completely seamless - eliminating grout joints which are hard to clean and prone to fail. Since this first bathroom was done the service station chain has refurbished all of its bathrooms, in house, with the **ADVANCED** system.

We Solve Your Toughest Surface Protection,  
Repair and Maintenance Problems  
On Budget... On Time... Every Time™

Copyright 2000

[www.AdvancedGroupUSA.com](http://www.AdvancedGroupUSA.com)

**ADVANCED**  
Polymer Repairs™

**856-691-7343**