

Project Profile

Casino Coin Count Room



The coin count room in this Atlantic City casino suffered damage from the heavy coin carts - over 2,000 lbs. The area had been repaired several times using conventional, inexpensive products with no success. The casino had to eventually cover the repairs with steel plates. Fearing one of the heavy carts might tip over and injure someone after encountering one of the many pot holes, the casino called in **ADVANCED POLYMER REPAIRS**.

The repairs were carried out in two days using an odorless product which has a 12,000 psi compressive strength.. The casino staff is pleased with their new, long lasting floor system. **ADVANCED** ..has also done similar work on the casino floor in areas where the coin collection "train" causes extensive damage to the concrete under the carpeting.



On Budget
On time
Every Time

ADVANCED
Polymer Repairs

856-691-7343

