

## Project Profile Air Handler Condensate Pan Corrosion



This 600,000 square foot office tower was experiencing corrosion in its air handler condensate pans. **ADVANCED Polymer Repairs** was called in to stop the corrosion before the damage caused leaks and costly replacement. **ADVANCED** installed a high performance, anti-corrosive product designed to adhere to manually prepared galvanized steel. This same anti-corrosive system is used on major bridges throughout the United States and around the world. The **ADVANCED** crew can recommend cost effective solutions for nearly any corrosion situation you might encounter.

We Solve Your Toughest Surface Protection,  
Repair and Maintenance Problems  
On Budget... On Time... Every Time™

Copyright 2000

[www.AdvancedGroupUSA.com](http://www.AdvancedGroupUSA.com)

**ADVANCED**  
Polymer Repairs™

**856-691-7343**