

Project Profile Concrete Step Restoration



This hospital needed to repair this entrance and eliminate the failing tiles which were causing a tripping hazard. Closing down this doctor's entrance for demolition and new concrete would have shut down the entrance for a month and was not an option. **ADVANCED Polymer Repairs** was called in when the facility manager heard of our success in similar projects in other facilities. Working over a long weekend, **ADVANCED** removed all tiles, repaired the concrete and coated the entire area with a high performance coating system which is flexible enough to move during temperature changes and is completely impervious to salt and other ice removal chemicals.

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

Copyright 2000

www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

856-691-7343