

## Project Profile Fountain / Waterfall Restoration



When the concrete inside this fountain / waterfall began to fail after only two years, **ADVANCED Polymer Repairs** got the call. This prestigious regional cancer center needed a company which not only knew how to repair and seal concrete but one which could get the job done quickly and with no impact on severely ill cancer patients. Because of the trust built over the years and after many successful projects, the facility manager knew he could count on **ADVANCED** to “do it right”. Tenting was erected so the repairs could be carried out in late winter. Extraordinary products, highly trained staff and years of experience make **ADVANCED** the “No Risk” choice.

We Solve Your Toughest Surface Protection,  
Repair and Maintenance Problems  
On Budget... On Time... Every Time™

Copyright 2003

[www.AdvancedGroupUSA.com](http://www.AdvancedGroupUSA.com)

**ADVANCED**  
Polymer Repairs™

**856-691-7343**