


## Project Profile Chiller Tube Sheet Face Repair



Tube sheet face erosion and corrosion are common problems with chillers and heat exchangers. The **ADVANCED Polymer Repairs** crew has done over 1,000 such repairs in the past 12 years. Most are still in service with little or no additional maintenance. Our specialty, ceramic enhanced products and knowhow insure long term solutions to tough surface protection problems like this in:

**Commercial Chillers**

**Refineries**

**Chemical Plants**

**Nuclear Power Plants**

**Fossil Power Plants**

**... and many more.**



We Solve Your Toughest Surface Protection,  
Repair and Maintenance Problems  
On Budget... On Time... Every Time™

**ADVANCED**  
Polymer Repairs™  
**856-691-7343**