

Project Profile Kettle Line Repair & Sealing



This hospital kitchen needed a permanent fix for their kettle line drain. Tile around the drain was constantly failing due to water getting into the transition between the tile and the drain. The director of facilities was tired of “fixing it over and over”.



ADVANCED Polymer Repairs was called in because of a long history of successful projects with the hospital. All of the tiles were removed along with the failing concrete. A 100% epoxy repair system was installed with an elastomeric sealer immediately surrounding the drain. This sealer is the key to a long lasting repair. The expansion joint it creates allows the drain and surrounding tile to expand and contract at their own rates when a large kettle of 200 degree water is emptied.

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

Copyright 2000

www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

856-691-7343