

Project Profile Cooling Tower Piping



When the insulation around these pipes was removed for inspection everyone was surprised at the amount of corrosion that had occurred. Since the cooling tower had to go online within a few days **ADVANCED Polymer Repairs** was called in. With little time to spare, the **ADVANCED** crew went straight to work. A high-performance anti-corrosive epoxy was applied. This coating is the same one being used by major bridge and highway authorities throughout the United States and the world. Think of **ADVANCED Polymer Repairs** for all of your corrosion problems -

- * Cooling Towers
- * Structural Steel
- * Air Handlers
- * Condensate Pans
- * Steel Roofing and Siding
- * Storage Tanks



We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

Copyright 2000

www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

856-691-7343