

Project Profile Casino Luxury Suite - Outdoor Deck



When this Atlantic City Casino deck started wicking water into the guest room

ADVANCED Polymer Repairs got the call. Over 4" of previous repairs had to be removed and a new, breathable system had to be installed and pitched to the only drain on this 250 s.f. deck.



A unique and breathable system sealed the deck and allowed the water saturated concrete to dry out without damaging the repair.

ADVANCED has many years of know how on solving the most challenging problems with excellent results

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

Copyright 2000

www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

856-691-7343