

Project Profile Flake Floor System



This hallway was in bad shape when the **ADVANCED Polymer Repairs** team was called in. Failing concrete, lifting tiles and dark carpeting left the area bleak and dull. Also, the carpet was installed over tile which was not well adhered. The tile started to lift causing lumps, creating a tripping hazard.



The problem was solved by **ADVANCED Polymer Repairs**. Carpeting and tiles were removed. Failing concrete was demolished until sound concrete was reached. A very attractive and long wearing "flake" floor system was then installed giving a terrazzo appearance for a fraction of the price. The hallway has been transformed from a dark dungeon to a bright, attractive and easy to care for showpiece.

On Budget

On Time

Every Time

ADVANCED
Polymer Repairs

856-691-7343

