

Project Profile Food Staging Room Floor



This casino had chronic problems keeping this refrigerator box staging area clean. Because the cooler was used to store seafood, any leakage onto the floor would penetrate the VCT tile joints and cause an unacceptable odor. Also, the heavy pallet traffic was damaging the tiles causing frequent repairs.



The casino had a long record of successful projects with **ADVANCED Polymer Repairs** on other projects so they turned to **ADVANCED** for a long-term solution. The problem was solved with a very strong yet flexible abrasion resistant coating system which will provide years of trouble free service.

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

856-691-7343