

## Project Profile Outdoor Fountain Rehab



This hospital fountain had sustained much damage from freeze / thaw cycles. **ADVANCED Polymer Repairs** has rebuilt many fountains with long lasting results using years of know how and the finest possible repair products. In this

case, a unique flexible epoxy was chosen as a base / sealer. This epoxy bonds tenaciously to almost any substrate and

will not crack from normal expansion and contraction. Two hybrid polyurethane coats were applied on top to provide UV stability and achieve the color chosen by the customer.

Know how and excellent products make **ADVANCED Polymer Repairs** the safe choice.

We Solve Your Toughest Surface Protection,  
Repair and Maintenance Problems  
On Budget... On Time... Every Time™

Copyright 2005

[www.AdvancedGroupUSA.com](http://www.AdvancedGroupUSA.com)

**ADVANCED**  
Polymer Repairs™

856-691-7343