

Project Profile

Acid Vapor Attack, Pharmaceutical Plant Walls



This *Fortune 100* pharmaceutical company was experiencing damage to the walls in several plants due to periodic release of acid fumes into the reactor area of their process. It was unable to find a coating that would stand up to the chemical attack.

ADVANCED Polymer Repairs had a long term relationship with the company and was asked to evaluate the problem and come up with a solution.

Fortunately, **ADVANCED** had a coating system that was designed for exactly this situation. A chemical resistant hybrid polyurethane was specified and the company asked **ADVANCED** to perform the surface preparation and installation.

The company evaluated the coating for a year then specified it for all similar areas.



www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

856-691-7343

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

Copyright 2000