


Project Profile

Kitchen Floor & Drains



When this hospital contacted **ADVANCED Polymer Repairs** their kitchen floor was in poor condition. Each of the 16 drains was leaking to areas below, grout was being replaced frequently - in some areas once a month, and the health inspector was not happy. The facility manager was desperate to repair the problem but **COULD NOT SHUT THE KITCHEN DOWN** while the work was being done



The problem was solved by **ADVANCED Polymer Repairs**. Relying on our many years of experience with problems just like this and products designed specifically for long service and quick turn-around we were able to keep the kitchen fully functional while repairs were being carried out.

Problem solved!

On Budget
On Time
Every Time

ADVANCED
Polymer Repairs

856-691-7343

