

Project Profile Cooling Tower, Seal and Corrosion Proof



The **ADVANCED Polymer Repairs** crew has repaired hundreds of cooling towers from coast to coast over the years. Corrosion, failing pan joints and split seams are very common problems.

Repairing leaking cooling towers can save owners tens of thousands of dollars while extending the life of these components for many years.



ADVANCED Polymer Repairs know how and unique repair systems are the safe way to repair cooling towers and related components in:

Power Plants

Commercial Buildings

Manufacturing Plants

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

Copyright 2000

www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

856-691-7343