


Project Profile Dishwasher Area Grout Repair and Sealing



After checking references and looking at similar work, this hospital chose **ADVANCED Polymer Repairs** to repair badly eroded grout joints and to seal this kitchen floor to stop persistent leaks to the area below. **ADVANCED** brought years of experience and some



very unique, high-performance epoxy systems to this job. Working over a weekend, **ADVANCED** repaired all of the eroded grout and sealed all drains and penetrations with an elastomeric sealing system that allows the floor to expand and contract around the drains without cracking and leaking.



ADVANCED Polymer Repairs has repaired and sealed many high use kitchen floors like this one in casinos, prisons, hospitals and food processing plants. Give us a call for a free evaluation of your kitchen floor problems and stop the leaks and hassle for good.

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

Copyright 2004

www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

856-691-7343