

Project Profile Grout Erosion & Tile Failure - Dishwasher



While **ADVANCED Polymer Repairs** has many years of experience repairing damaged kitchen floors we learn from our customers occasionally. Here, one of our best customers needed a quick and inexpensive yet permanent fix to



this floor which was leaking into the casino area below. Using one or our 100% epoxy sealers they added commonly available concrete color to achieve the quarry tile

red color. This chronic problem was repaired quickly, the leak was stopped, the health inspector satisfied and the dish wash area returned back to service. GOOD JOB GUYS!

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

ADVANCED
Polymer Repairs™

856-691-7343