

Project Profile Casino Kitchen / Kettle Line



This Atlantic City casino has used **ADVANCED Polymer Repairs** on its toughest repair problems. Here we rebuilt their kettle line floor - an area of constant problems



Tiles were replaced with a 100% epoxy repair product, grout joints were sealed as were all penetrations and kettle bases. The drain areas were completely rebuilt and sealed with an elastomeric product.

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

ADVANCED
Polymer Repairs™

856-691-7343