

# Project Profile

## Production Bakery, Atlantic City Casino



When the Director of Facilities for this casino needed help solving a floor problem in the production bakery which services two casinos he turned to **ADVANCED Polymer Repairs** for a solution. After many successful projects with **ADVANCED** over the years, he knew he could trust them to fix it right and to treat him fairly. While the floor appears to be in good condition it had been penetrated by water from a crack near a steam kettle (inset left). The water then migrated throughout much of the floor underneath the quarry tile and grout



It had traveled over 30 feet and would ooze out of seemingly sound areas when walked on (inset left). Keeping the kitchen open was critical so **ADVANCED** did the work in stages while working over a long weekend. Some stages required work to proceed nonstop for 20 hours straight. The floor was returned to service with only minimum disruption to the bakery's production. **ADVANCED** is "the safe choice" for a variety of problems.

We Solve Your Toughest Surface Protection,  
Repair and Maintenance Problems  
On Budget... On Time... Every Time™

Copyright 2000

[www.AdvancedGroupUSA.com](http://www.AdvancedGroupUSA.com)

**ADVANCED**  
Polymer Repairs™

**856-691-7343**