

Project Profile - Sealing Leaking Showers



LEAKING SHOWERS are common problems in many **Hospitals, Nursing Homes, Colleges, Universities and Prisons**

The **ADVANCED** team permanently repaired hundreds of showers. The first such repair was carried out over eight years ago and looks great after years of hard use.



Using a low odor, high performance coating system, all grout joints are first repaired and then all surfaces are completely covered with a polyurethane coating that adheres tenaciously to glazed ceramic tiles, quarry tiles, concrete, brick and block. Maintenance costs are completely eliminated. Cleaning costs are slashed dramatically because of the nonporous nature of the coating.

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

ADVANCED
Polymer Repairs

856-691-7343™

