

Project Profile Step Rebuilding and Protection



The elements and deicing salt had taken a toll on these steps. **ADVANCED Polymer Repairs** was called in to provide a long term repair. The concrete landing was severely damaged and a previous repair attempt proved only temporary. With its many years of experience in the repair of concrete steps **ADVANCED** was able to completely repair and resurface these steps for just a fraction of the demolition costs alone if a traditional concrete replacement had been used. Demolition, landscaping and down time are all factors that should be considered



when calculating the cost of various repair methods. The system specified by **ADVANCED** has been used for many years. It is extremely durable, attractive and is completely unaffected by deicing chemicals and salt. The total repair was carried out over a weekend with no downtime for access.

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

ADVANCED
Polymer Repairs™

856-691-7343