

Project Profile Seal Floor, Mechanical Room, Sterilizers



This hospital called **ADVANCED Polymer Repairs** to seal the mechanical room for their large sterilizers. Water was finding its way into public areas below and was causing damage to ceilings and walls for some time. Working on a very tight schedule, the **ADVANCED** crew used a combination of high performance sealing systems to seal the floor as well as all penetrations. The problem was solved and further damage avoided.

ADVANCED Polymer Repairs has many years of experience in sealing and stopping the most challenging leaks.

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

Copyright 2000

www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

856-691-7343