

## Project Profile Concrete Sidewalk, Repair & Slip Proof



The sidewalk at the corporate headquarters of an auto manufacturer was failing. It had become a tripping hazard and because of existing landscaping, the need to maintain the entranceway and the fact that this sidewalk was electrically heated normal demolition and concrete replacement were not an option.

**ADVANCED Polymer Repairs** knew this

project would be very challenging because of the work schedule - certain hours on weekends and nights with the sidewalk open for use by 6:00 AM each day.

Using high performance, fast curing products and years of know how, the **ADVANCED** team met the schedule with a beautiful and functional result.



We Solve Your Toughest Surface Protection,  
Repair and Maintenance Problems  
On Budget... On Time... Every Time™

Copyright 2000

[www.AdvancedGroupUSA.com](http://www.AdvancedGroupUSA.com)

**ADVANCED**  
Polymer Repairs™

**856-691-7343**