

Project Profile Repair and Protect Trash Compactor Floor



This trash compactor services a 17 story dorm tower at a major university. Years of damage from the heavy dumpsters and chemical attack from leaking trash juices had taken their toll on the concrete floor. **ADVANCED Polymer Repairs** was asked to repair the floor during a brief shutdown of the room to change out the compactor. Working on a tight schedule **ADVANCED** installed a drain under the compactor area and connected it into an existing drain. The spalled and damaged concrete was repaired using a proprietary, 100% epoxy concrete repair system. The entire floor was coated with a chemical resistant system and seamless, epoxy cove bases installed to contain water used to wash the area.

www.AdvancedGroupUSA.com

ADVANCED
Polymer Repairs™

• 856-691-7343

We Solve Your Toughest Surface Protection
Repair and Maintenance Problems
On Budget... On Time... Every Time™

Copyright 2000