

## Project Profile Corrosion, Lube Oil Cooler



This electric utility had used **ADVANCED Polymer Repairs** for many projects over the years. When this lube oil cooler on their gas turbine generator started to show signs of corrosion **ADVANCED** got the call. Because this generator earns the utility a large income during the summer months, the work schedule was tight..



The plant manager was very pleased with the work and the result. Because of our long term and successful relationship, the plant manager knows that the work is being done “by the book” even if he’s not there to supervise.

**On Budget  
On Time  
Every Time**

**ADVANCED**  
Polymer Repairs

**856-691-7343**





