

## Project Profile Concrete Repair, Electric Utility Generator



When a contractor dropped the 10 ton containment structure which houses this combustion turbine generator, the concrete footing was severely damaged. Unable to operate the generator and facing lost revenue of over \$100,000 per day using concrete would have shut the generator down for at least a week. The utility called in **ADVANCED Polymer Repairs**. Having used **ADVANCED** on other critical projects, they knew the repair could be carried out quickly. Using a fast curing, high strength (12,000 psi) epoxy concrete repair system, the generator was back on line on the third day.

We Solve Your Toughest Surface Protection,  
Repair and Maintenance Problems  
On Budget... On Time... Every Time™

Copyright 2000

[www.AdvancedGroupUSA.com](http://www.AdvancedGroupUSA.com)

**ADVANCED**  
Polymer Repairs™

**856-691-7343**