

Project Profile High Temperature Corrosion Coating



The exhaust stack of this gas turbine generator reaches temperatures of 1,100 degrees F. Corrosion was taking a severe toll and **ADVANCED Polymer Repairs** was called in. The **ADVANCED** crew grit blasted all surfaces clean and applied two coats of a coating designed to withstand the extreme temperature.

On Budget
On Time
Every Time

Copyright ProjProf.04.04

ADVANCED
Polymer Repairs

856-691-7343

