


Project Profile Corrosion, Air Conditioner / Heater



This facility had a problem with their individual room air conditioner / heater units. The condensate pans were heavily corroded and some looked more like swiss cheese than steel. **ADVANCED Polymer Repairs** was called in for a fix. **ADVANCED** has extensive experience in dealing with corrosion in HVAC systems and specified a product which would completely encapsulate the pans, completely stopping any further corrosion. The property manager was able to repair



the units instead of replacing them as they had in the past. Over 500 units were scheduled for replacement. This solution saved the property over \$300,000. The product specified is very easy to apply and is virtually odorless.

We Solve Your Toughest Surface Protection,
Repair and Maintenance Problems
On Budget... On Time... Every Time™

ADVANCED
Polymer Repairs™

856-691-7343